

From: Chris Collyer chris@playsafeplaygrounds.co.uk
Subject: RE: Stedham inspection
Date: 3 September 2018 at 11:08
To: Jane Crawford clerk@stedhamwithiping-pc.gov.uk

CC

Morning Jane

Please see the attached inspections for the two play areas. The Green play area has just one or two things to monitor. The Common View play area has a couple of items that need to be looked at as a matter of urgency.

- Log on log chain needs to be replaced - see attached pictures;
- Log on large suspension bridge needs to be replaced - see attached pictures;

Let me know if you need us to make these repairs and we will get things moving as soon as possible.

Kind Regards

Chris

Chris Collyer
Playsafe Playgrounds Ltd
T: 01730 815472
W: www.playsafeplaygrounds.co.uk

PLAYSAFE PLAYGROUNDS

Independent Playground Designer, Supplier, Installer and Safety Surfacing Specialist

T: 01730 815472

F: 01730 815872

W: www.playsafeplaygrounds.co.uk

E: enquiry@playsafeplaygrounds.co.uk

SafaMulch™
"The Safe Choice"

-----Original Message-----

From: Jane Crawford [<mailto:clerk@stedhamwithiping-pc.gov.uk>]

Sent: 07 February 2018 11:25

To: Chris Collyer

Subject: Stedham inspection

Hello Chris,

Attached is our order for our play areas inspection.

Hope all is well with you.

Best wishes

Jane
Clerk, Stedham with Iping Parish Council

This email has been checked for viruses by AVG.
<http://www.avg.com>

PLAYSAFE PLAYGROUNDS Ltd.
INSPECTION WORKSHEET

CLIENT ORGANISATION: Stedham Parish Council	
SITE ADDRESS: Common View Play Area, Stedham	
INSPECTION CARRIED OUT BY: Chris Collyer	INSPECTION DATE: 25/08/2018
CLIENT CONTACT: Jane Crawford	CLIENT CONTACT No.: 01730 812177

ITEM No.	EQUIPMENT DESCRIPTION	MANUFACTURER	YEAR	DEFECTS	WORKS REQUIRED
1	SLIPPER LEG	Unknown	Unknown	Signs of rot Seams and patch holes visible Wear on top of legs where chain sits Seams surfaces could become slippery	Monitor Monitor for seams splitting above chain Monitor for 40% + wear Consider degrading / replace if needed
2	Slipper Bridge	Unknown	Unknown	Wear on top of legs where chain sits Seams surfaces could become slippery	Monitor for 40% + wear Monitor
3	Circle Chains	Unknown	Unknown	Spills to timber Signs of rot on top of legs Wear on top of legs where chain sits	Monitor Monitor Monitor for 40% + wear
4	Log Chain	Unknown	Unknown	Spills to timber Signs of rot Wear on top of legs where chain sits 1 x hanging log has split and broken, requiring the bolt	Monitor Monitor Monitor for 40% + wear Replace immediately
5	Slipper Legs	Unknown	Unknown	Top can become slippery over time 1 No slipper legs in ground Signs of rot	Check and consider cross cut Monitor - wear if visible on bottom Monitor
6	Seat Flat Seat Swing	Wicksteed	Unknown	Seams in joints visible Wearing grass mat under swing seats, mats pulling apart	No action required Rectify ASAP as problem will only worsen with use
7	Free Standing Slide	Unknown	Unknown	Paint starting to flake in small areas No defects	Monitor and repaint when deemed necessary -
8	Circle Climber	BH Ltd and son	Unknown	Showing signs of rust No defects	Monitor for further rust, treat if needed -
9	Superman Bridge	Unknown	Unknown	Timbers splitting with small parts breaking off across the unit Possible splintering Signs of rot across the unit Seams have more potential to be slippery 1 No bridge has broken due to rot and the chain lying is wedged around the hand rail	Monitor for further rot, replace if needed Monitor on regular basis Monitor on regular basis Clean and treat The legs need to be replaced ASAP and the slip chain matched
10	Spring Surf Board	Playdale	2015	No defects	-

PLAYSAFE PLAYGROUNDS Ltd.
INSPECTION WORKSHEET

CLIENT ORGANISATION: Stedham Parish Council	
SITE ADDRESS: The Green Play Area, Stedham	
INSPECTION CARRIED OUT BY: Chris Collyer	INSPECTION DATE: 25/08/2018
CLIENT CONTACT: Jane Crawford	CLIENT CONTACT No.: 01730 812177

ITEM No.	EQUIPMENT DESCRIPTION	MANUFACTURER	YEAR	DEFECTS	WORKS REQUIRED
1	Single flat seat swing	Unknown	Unknown	Wear to chain links Safety surfaces wear under seat at	Monitor for 40% + wear Monitor
2	Free standing slide	SUTCLIFFE PLAY	Unknown	Light rust to slide at slide entry 2 x missing nut caps - M10 No defects	Monitor Replaced -
3	Cradle Seat Swings	Sutcliffe Play	2008	Light rust to top beam pivots No defects	Monitor -
4	Trapdoor Rings	Playdale	2015	Missing bolt caps x2 No defects	Replaced -
5	Spring Surf Board	Wicksteed	2015	No defects	-
	Safety Surf Board	-	-	No defects	-







